


T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
MC# 22 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Bearing Trees	
Species <u>TAM.</u>	<u>TAM.</u>
Diameter <u>6"</u>	<u>4"</u>
Bearing <u>N30E</u>	<u>S70E</u>
Distance <u>10 LKS</u>	<u>15 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1986-1987 By Gary Stevenson
Location filed Corner Certificate - Doc # 295279
Monument Find 2 x 60" i.p. w/ brass cap per old certificate - this certificate made to update old certificate.

Evidence of Subsequent Corner Restoration

Year of search 1963 By OKerman
Corner Certificate
Find squared scribed post

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>ASH</u>	<u>Elm</u>	<u>Elm</u>
Diameter	<u>6"</u>	<u>14"</u>	<u>8"</u>	<u>14"</u>
Bearing	<u>N82°E</u>	<u>S80°E</u>	<u>S62°E</u>	<u>S45°E</u>
Distance	<u>61.40'</u>	<u>144.30'</u>	<u>48.20'</u>	<u>94.64'</u>

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Elm</u>
Diameter	<u>6"</u>	<u>8"</u>
Bearing	<u>N82°E</u>	<u>S62°E</u>
Distance	<u>61.4'</u>	<u>48.2'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1963
Certificate - Gary Stevenson - 1987 - update