


T. 142 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 12 Corner common to sections 1, 12



O = Corner

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1872  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>CEDAR</u>	<u>8"</u>	<u>14"</u>	
<u>21 LKS</u>	<u>N66W</u>	<u>543w</u>	<u>6 LKS</u>

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
 Year of search 1997 By Laverne Leuelling  
Set alum. capped alum. rod online between the SW corner of Sec. 1 & a theoretical SE corner of Sec. 1  
Cert. Filed: June 1, 1998; Doc. # 400497

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects			
<u>Ash</u>	<u>Ash</u>	<u>Steel Signpost</u>	<u>Ash</u>
<u>0.229m</u>	<u>0.102m</u>	<u>E</u>	<u>0.203m</u>
<u>N55W</u>	<u>S76W</u>	<u>E</u>	<u>N67E</u>
<u>6.075m</u>	<u>5.988m</u>	<u>0.440m</u>	<u>9.386m</u>

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_