


Index No. J 17-18

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5th Coordinates: X _____ Y _____
M.C.# 18 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>NORWAY SPRUCE</u>	<u>?</u>	Bearing	<u>SPRUCE</u>	Trees	_____
Diameter	<u>4"</u>			<u>8"</u>		_____
Bearing	<u>N79E</u>			<u>S81E</u>		_____
Distance	<u>13 LKS</u>			<u>5 LKS</u>		_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1997 By Laverne Leuelling
Aluminium capped aluminium rod
was set at position of sandpoint.

Cert. Filed: June 1, 1998; DOC. 400495

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>White Birch</u>	<u>OAK</u>	<u>White Birch</u>
<u>0.300m</u>	<u>0.155m</u>	<u>0.218m</u>
<u>S80E</u>	<u>N73E</u>	<u>N18E</u>
<u>9.408m</u>	<u>3.964m</u>	<u>7.658m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____