


T. 142 R. 26 M. 574 Coordinates: X _____ Y _____
N 1/4 14 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species FIR N. PINE
Diameter 8" 8"
Bearing S 42 E N 75 E
Distance 13 Lks 7 Lks

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1984 By Freeman-Hammitzsch
Location filed Survey Tech - Forest
Monument Find USFS Concrete man i brass cap - also Birch S 57 E 45.3'

Evidence of Subsequent Corner Restoration

Year of search 1963 By B. I. Okerman
Corner Certificate
Find orig B.T. Stump N 75 E, also found 2" I.P. set by County Surveyor Flynn - according to Clarence Van Atta, also found possible orig cedar post w/ scribing set 6" x 60" concrete cylinder w/ cap

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Birch Rock Cedar post
9" 3x3x2 4x4x60
S 57 E N 31 W Due North
45.3' 113.5'
w/ "X"

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1963

Oct. 1996 - Found, accepted, & maintained 1963 USDA-FS perpetuation of the original G.L.O. quarter corner.
Cert. Filed: June 1, 1998; Doc # 400494

X Rock - 3x3x2, N31W, 113.32; Oak, 0.152m.
S40W, 6.544m; 9" Birch snag, S59E,
45.17'; Pine stump, N64E, 5.8'; Ash,
0.127m, N42E, 10.461m

1999 - (C of S #485) Landecker notes that the Brass cap monument was found impl.

Oct. 2003 M. Stefan #12261
Cert. of Sur. shows brass cap mon. found