


Index No. J 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	N. PINE	N. PINE	N. PINE	N. PINE
Diameter	<u>16"</u>	<u>16"</u>	<u>16"</u>	<u>16"</u>
Bearing	<u>N 43 W</u>	<u>N 60 E</u>	<u>S 43 E</u>	<u>S 41 W</u>
Distance	<u>29 LKS</u>	<u>11 LKS</u>	<u>30 LKS</u>	<u>34 LKS</u>

Original Bearing Trees Found			
Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1997 6-16 By Laverne Leuelling
Set brass capped galv. steel pipe.
Cert. Filed: Dec. 8, 1997; Doc. # 395051

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Aspen	Aspen	Aspen	Maple
<u>0.152m</u>	<u>0.152m</u>	<u>0.127m</u>	<u>0.229m</u>
<u>N 89 W</u>	<u>S 34 W</u>	<u>S 68 E</u>	<u>N 63 E</u>
<u>5.942m</u>	<u>1.965m</u>	<u>5.486</u>	<u>6.935m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____