


T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 13 Corner common to sections 17, 13



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>12"</u>	_____	_____
Bearing	<u>N8W</u>	<u>S30E</u>	_____
Distance	<u>10 LKS</u>	<u>29 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1997 June By Laverne Levelling
Set brass capped galv. steel pipe at the
"lost" position

Doc. Filed: Dec. 8, 1997; Doc. #395052

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>N Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
<u>0.457m</u>	<u>0.406m</u>	<u>0.406m</u>
<u>N80W</u>	<u>N21W</u>	<u>N77DE</u>
<u>2.194m</u>	<u>5.227m</u>	<u>5.512m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____