


Index No. L 17

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 14 15 Corner common to sections 14, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>SPRUCE</u>	<u>SPRUCE</u>
Diameter	<u>10"</u>	<u>10"</u>
Bearing	<u>S 42 W</u>	<u>S 88 E</u>
Distance	<u>20 LKS</u>	<u>15 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1997, July By Laverne Luelling  
Monumented ctr. corner at intersection of  
line connecting E 14 corner, Sec. 16, and Center  
ctr. of Sec. 15.

Cert Filed: Dec. 8, 1997; Doc # 395055

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Birch</u>	<u>Birch</u>	<u>Balm of Gilead</u>	<u>Steel Sign</u>
<u>0.203m</u>	<u>0.203m</u>	<u>0.152m</u>	_____
<u>S 66 W</u>	<u>S 64 E</u>	<u>N 01 E</u>	<u>N</u>
<u>5.068m</u>	<u>2.070m</u>	<u>23.920m</u>	<u>1.130m</u>

Subsequent Corner Restoration

Year surveyed Aug 2003 By L. Luelling # 16089  
Location filed \_\_\_\_\_  
Monument Cert of Surv. shows Mon. Found

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_