


T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
MC # 8 Corner common to sections 13,14



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species N. PINE N. PINE
 Diameter 8" 6"
 Bearing N67W S15W
 Distance 13 LKS 15 LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1997, June By Laverne Leuelling
Perpetuated this corner, which had an intact
Civilian Conservation Corps bearing tree
+ a Cass Co. pipe.
Cert. Filed: Dec. 8, 1997; Doc. # 395059

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>Oak</u>	<u>N. Pine</u>	<u>Ash</u>	<u>St. Signpost</u>
<u>0.142m</u>	<u>0.490m</u>	<u>0.091m</u>	
<u>S60E</u>	<u>N46W</u>	<u>N11W</u>	<u>E</u>
<u>11.760m</u>	<u>4.440m</u>	<u>11.800m</u>	<u>1.082m</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____