


Index No. N 15

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
N 14 22 Corner common to sections 15, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument POST

Species	Bearing	Trees
<u>N. PINE</u>	<u>ASDEN</u>	
<u>12"</u>	<u>10"</u>	
<u>N 33 E</u>	<u>S 33 W</u>	
<u>5 LKS</u>	<u>11 LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1916 By JAMES FLYNN
 Location filed COUNTY BOOK "C" P. 164
 Monument From OLD GOVT B.T.: STUMP 12" N. PINE N 33 E
5 LKS.

Evidence of Subsequent Corner Restoration
 Year of search 1963 By William Okerman
 Found 20" W. PINE N 47° 30' W 50.5'. Set
2" x 60" galvanized steel monument with
3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. PINE</u>	<u>N. PINE STUMP</u>	
<u>12"</u>	<u>8"</u>	
<u>N 47-30</u>	<u>S 20 W</u>	
<u>50.5'</u>	<u>42.8'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Tamarack</u>	<u>Cedar Post</u>	
<u>17"</u>	<u>4 x 4 x 60"</u>	
<u>S 25 W</u>	<u>North</u>	
<u>105'</u>	<u>2.4'</u>	

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - OKERMAN - 1963

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____