Index No. P-20

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5th Coordinates: X _____ Y _____

CE 116 Corner common to sections 23



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species				
Diameter				
Bearing				
Distance				

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1998 By Northern Lights

Location filed Cass Co. Recorder (T-34)

Monument USFS Brass Cap, set midway on line.

Steel Sign Post South, 3.1'

Bearing Trees, Reference Objects

Species	Tamarack	Tamarack	Spruce	Steel Post
Diameter	6"	5"	7"	
Bearing	N85°E,	N50°E,	S23°E,	East
Distance	46.55'	53.73'	58.54'	3.1'

Evidence of Subsequent Corner Restoration

Year of search 8/2000 By CCSO

Found & Located corner, 100'± W. of & CR #52.

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____