


Index No. R 15

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 27 Corner common to sections 22, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>MAPLE</u>	<u>Y. BIRCH</u>	_____
Diameter	<u>6"</u>	<u>5"</u>	_____
Bearing	<u>SSE</u>	<u>N12W</u>	_____
Distance	<u>12LKS</u>	<u>11LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1994 11-30 By Lowell Schellack  
Found nothing. On 1-10-95 placed a 2 1/2" dia. x 48  
galvanized iron monument w/ a 3" dia. brass cap -  
4" above ground.  
3-21-95 Cert. Filed by Lowell Schellack, RLS 15572  
Doc # 365502

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Ash</u>	<u>Ash</u>	<u>Maple</u>
<u>7"</u>	<u>7"</u>	<u>9"</u>
<u>N42E</u>	<u>N47W</u>	<u>S61E</u>
<u>23.73</u>	<u>27.80</u>	<u>14.69</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_