


T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
ML # 7 Corner common to sections 24, 25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. PINE</u>	<u>SPRUCE</u>	_____	_____
Diameter	<u>8"</u>	<u>6"</u>	_____	_____
Bearing	<u>N52E</u>	<u>S35E</u>	_____	_____
Distance	<u>5 LKS</u>	<u>3 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By JAMES FLYNN
Location filed COUNTY BOOK X " P415
Monument Find old Govt B.T.

Evidence of Subsequent Corner Restoration

Year of search 1997, May By Laverne Leuelling
Set galv. steel pipe w/ brass cap.
Cert. Filed: Dec 8, 1997; Doc. # 395074

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>W. PINE</u>	_____	_____
Diameter	<u>16"</u>	<u>10"</u>	_____	_____
Bearing	<u>N35E</u>	<u>S45E</u>	_____	_____
Distance	<u>16'</u>	<u>6'</u>	_____	_____

Bearing Trees, Reference Objects

<u>Norway Pine</u>	<u>W. Pine</u>	<u>N. Pine</u>	_____	_____
<u>0.622m</u>	<u>0.513m</u>	<u>0.533m</u>	_____	_____
<u>N38E</u>	<u>S29E</u>	<u>S37E</u>	_____	_____
<u>4.848m</u>	<u>1.712m</u>	<u>33.064m</u>	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____