


Index No. 55

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
N 116 Corner common to sections 29, 30



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1963 By William Okerman
Location filed _____
Monument Found 1 1/2" iron pipe. Set 6" x 60" cylindrical concrete monument with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species Burr Oak Burr Oak Cedar Post
Diameter 4" 5" 4" x 4" x 60"
Bearing N87E S14E East
Distance 21.5' 25.3' 4.2'

Evidence of Subsequent Corner Restoration

Year of search 1982 By G. LAND
FIND CONCRETE MON. w/ BRASS CAP.
15' S. OF RD.

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1963

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____