


Index No. A 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. R7 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 2 Corner common to sections 1, 2 AND 35, 36-143-27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing Trees			
	FIR	FIR	FIR	MAPLE
Diameter	<u>8"</u>	<u>8"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>S51W</u>	<u>N13W</u>	<u>N32E</u>	<u>S52E</u>
Distance	<u>39 LKS</u>	<u>23 LKS</u>	<u>24 LKS</u>	<u>18 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO

Location filed COUNTY BOOK "B" P. 455-462

Monument FIND OLD GOVT B.T.S: 8" BIRCH S51W 39 LKS, 6" FIR N32E 24 LKS, SET 4x4x48" CEDAR POST

also on microfilm - roll 115 BK 79 P. 17, 28-29

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSEM RLS #16089

Set a 2"x48" galv. steel pipe w/ brass cap, 7" above ground. Steel sign posts North, 1.93' and East, 1.96'

Bearing Trees, Reference Objects

Species	<u>SPRUCE</u>	<u>BIRCH</u>
Diameter	<u>7"</u>	<u>15"</u>
Bearing	<u>S27W</u>	<u>S76E</u>
Distance	<u>17.50'</u>	<u>15.30'</u>

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Maple</u>	<u>Basswood</u>	<u>W. Spruce</u>
Diameter	<u>7"</u>	<u>5"</u>	<u>13"</u>	<u>5"</u>
Bearing	<u>N84°W</u>	<u>N72°E</u>	<u>S8°E</u>	
Distance	<u>24.46'</u>	<u>11.27'</u>	<u>58.65'</u>	<u>56.65'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared  
Filed at CCRO Dec. #413181

By NLSEM  
Date 5/25/99