Index No. C 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____

E1/4 5 Corner common to sections 4,5



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	CEDAR	CEDAR		
Diameter	12"	7"		
Bearing	N73W	S43E		
Distance	8 LKS	6 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1920 By GLO

Location filed SEC. OF STATE

Monument NO ORIG. EVIDENCE SET 8' CEDAR POST, 6" SQUARE, 4' IN GROUND MARKED: 1/4 S5 ON W. SIDE, S4 ON EAST SIDE

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____