


Index No. K 9-10

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____

SMC ON Corner common to sections 16
N 1/4 LINE



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1920
Original monument 1x36" I.P. W/BRASS CAP

n 516 / N SMC
1920

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. OAK</u>	<u>W. OAK</u>	_____	_____
Diameter	<u>36"</u>	<u>28"</u>	_____	_____
Bearing	<u>S60 1/2 W</u>	<u>N18 1/2 W</u>	_____	_____
Distance	<u>12 LKS</u>	<u>167 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1979 By Gary Stevenson
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>W. OAK</u>	<u>W. OAK</u>	<u>NE Corner</u>
Diameter	<u>8"</u>	<u>41"</u>	<u>5"</u>	<u>con. post</u>
Bearing	<u>S50 W</u>	<u>S60 W</u>	<u>S21 W</u>	<u>North</u>
Distance	<u>94.30'</u>	<u>7.9'</u>	<u>106.05'</u>	<u>46.9'</u>

(1919 BT)

Bearing Trees, Reference Objects

Species	<u>SE Corner</u>	_____	_____	_____
Diameter	<u>con. post</u>	_____	_____	_____
Bearing	<u>N 73 W</u>	_____	_____	_____
Distance	<u>26.45'</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 21,4922