


T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
M.C. # 23 Corner common to sections 17, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>ASH</u>	<u>ELM</u>	_____
Diameter	<u>8"</u>	<u>8"</u>	_____
Bearing	<u>N40W</u>	<u>S82W</u>	_____
Distance	<u>76 LKS</u>	<u>89 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed SEC. OF STATE
Monument PROPORTIONAL POSITION IN LAKE SET 1436"
L.P. W/BASS CAP. T142N

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>BIRCH</u>	_____
Diameter	<u>14"</u>	<u>14"</u>	_____
Bearing	<u>N77 1/2 W</u>	<u>S88 1/2 W</u>	_____
Distance	<u>156 LKS</u>	<u>251 LKS</u>	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____