


T. 142 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 27 Corner common to sections 22, 23, 26, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>FIR</u>	<u>FIR</u>	<u>POPULAR</u>	<u>POPULAR</u>
Diameter	<u>6"</u>	<u>7"</u>	<u>8"</u>	<u>5"</u>
Bearing	<u>N70E</u>	<u>S58W</u>	<u>N25W</u>	<u>S10E</u>
Distance	<u>6 LKS</u>	<u>18 LKS</u>	<u>8 LKS</u>	<u>21 LKS</u>

Original Bearing Trees Found				
Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1981 By GARY STEVENSON  
Location filed PLAT OF SURVEY "E-74"  
Monument REPLACED 2" I.P. WITH 2" X 60" GALV. I.P. W/ 3" BRASS CAP.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects				
Species	<u>BALSAM</u>	<u>BALSAM</u>	<u>BALSAM</u>	<u>BALSAM</u>
Diameter	<u>10"</u>	<u>5"</u>	<u>10"</u>	<u>12"</u>
Bearing	<u>NORTH</u>	<u>S65E</u>	<u>S3W</u>	<u>WEST</u>
Distance	<u>8.04'</u>	<u>18.65'</u>	<u>9.85'</u>	<u>9.83'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - GARY STEVENSON - 1981  
Doc. # 260593

April 1915; Twp Rd order shows no survey