


T. 142 R. 27 M. 574 Coordinates: X _____ Y _____
E 1428 Corner common to sections 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trass
<u>POPULAR</u>	<u>BL. OAK</u>	
Diameter <u>6"</u>	<u>8"</u>	
Bearing <u>S 48 E</u>	<u>N 80 W</u>	
Distance <u>15 LKS</u>	<u>33 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1981 By GARY STEVENSON
Location filed PLAT OF SURVEY "E-74"
Monument FOUND A US GLO BRASS CAPPED MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO
SET 1x36" I.P. W/BRASS CAP PROPORTIONALLY
1/4
528/527
1919

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>R. OAK</u>	<u>R. OAK</u>	<u>R. OAK</u>
Diameter <u>6"</u>	<u>6"</u>	<u>8"</u>
Bearing <u>N 5 E</u>	<u>S 56 W</u>	<u>EAST</u>
Distance <u>24.10'</u>	<u>3.41'</u>	<u>23.15'</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>POPULAR</u>	<u>R. OAK</u>	
Diameter <u>10"</u>	<u>6"</u>	
Bearing <u>S 3 E</u>	<u>N 72 1/4 W</u>	
Distance <u>191 LKS</u>	<u>97 LKS</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. # 260596
Found GLO monument in good condition.
14" R. OAK N 72 W 64.0' (1919 BT); 6" R. OAK
S 56 W 3.41'; 6" R. OAK N 5 E 24.10'; 8"
R. OAK East 23.15'.