


Index No. V6-7

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
M.C.# 57 Corner common to sections 29,32



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1873  
Original monument Post

**Bearing Trees**

Species NO B.T.  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

O = Corner

**Subsequent Corner Restoration**

Year surveyed 1919 By GLO  
Location filed SEC. OF STATE  
Monument PROPORTIONAL PRINT FOR M.C. IN LAKE. SET  
1X36" I.P. W/BRASS CAP  
T142N  
mc | 529  
532  
R27W

**Bearing Trees, Reference Objects 1919**

Species	<u>W. OAK</u>	<u>W. OAK</u>
Diameter	<u>16"</u>	<u>16"</u>
Bearing	<u>N62 1/4 E</u>	<u>S78 1/2 E</u>
Distance	<u>69 LKS</u>	<u>120 LKS</u>

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_