


Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X Y  
N114 4 Corner common to sections 4 AND 33-143-28



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1873  
 Original monument Post

Species	Bearing	Trees
<u>W OAK</u>	<u>IRONWOOD</u>	
Diameter <u>12"</u>	<u>4"</u>	
Bearing <u>S30E</u>	<u>N15W</u>	
Distance <u>14LKS</u>	<u>13LKS</u>	

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance

**Subsequent Corner Restoration**  
 Year surveyed 1928 By GLO  
 Location filed SEC. OF STATE  
 Monument END ORIG. B.T.S. 16" OAK STUMP S20E 14LKS,  
24" W OAK STUMP S75W 15LKS SET 1X36" I.P.  
W/BRASS CAP 114 533  
54  
1928

**Evidence of Subsequent Corner Restoration**  
 Year of search 1982 By Gary Stevenson  
 Found GLO monument in good condition.  
Dec. 1923, Twp rd order shows no survey.

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>MAPLE</u>	<u>7"</u>	<u>N66-15E</u>	<u>53LKS</u>
<u>MAPLE</u>	<u>8"</u>	<u>S4-15W</u>	<u>32LKS</u>

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>11"</u>	<u>N44W</u>	<u>56.51'</u>
<u>Maple</u>	<u>13"</u>	<u>N68E</u>	<u>35.0'</u>
<u>Maple</u>	<u>11"</u>	<u>N81E</u>	<u>55.34'</u>
<u>Ash</u>	<u>11"</u>	<u>S39W</u>	<u>133.04'</u>

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - Gary Stevenson - 1982  
Doc. # 264926  
corner GPS ccsso 12/4/02  
ccso 12/4/02 Fd GLO Brass cap Mon,  
down 0.1', 24" ± N. of 2