


Index No. A 16

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 116 Corner common to sections 3 AND 34-143-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1928  
Original monument 1x36" 1/4" W BRASS E 116 S 34  
CAP 1928

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Poplar Poplar \_\_\_\_\_  
Diameter 4" 4" \_\_\_\_\_  
Bearing S 8-30 E N 84 W \_\_\_\_\_  
Distance 69 LKS 47 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1982 By Gary Stevenson  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search Dec. 1933 By \_\_\_\_\_  
Typed order shows no survey

Bearing Trees, Reference Objects

Species R. Oak Ash Ash  
Diameter 13" 7" 10"  
Bearing N 29 W S 2 W S 18 W  
Distance 100.55' 121.20' 87.0'

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - Gary Stevenson - 1982  
Doc. # 264928

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_