


Index No. B11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 57A Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.N. 116 Corner common to sections 4



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1928  
Original monument 1x36" I. Pin/BASS N116 1 54  
192

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species MAPLE MAPLE \_\_\_\_\_  
Diameter 18" 12" \_\_\_\_\_  
Bearing N10 30E S87W \_\_\_\_\_  
Distance 33 1/2 36 1/2 \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_