Index No. C 13 CASS COUNTY LAND	CORNER RECORD	
T. 142 R. 28 M. 57H Coordinates: X E14 4 Corner common to sections 3, 4	Y	
E 19 7 Corner common to sections 27		
	SURVEYS	1 7 1 4
Original Government Survey	Original Evidence Found	
Year surveyed 1874	Year of searchBy	
Original monument Post	Monument found	
The same of the sa	Original Bearing Trees Found	O = Corner
Species Serve Maple Diameter 9" 8"	Species	O Designation of the second of
Digmeter 9" 8"	Diameter	
Pagrica NSEE N/SW	Bearing	
Distance 25 CKS 6 CKS	Distance	
Colonia Colonia Colonia	Fuidance of Substitute C	anna Dantanakan
Subsequent Corner Restoration Year surveyed 1928 By 640	Evidence of Subsequent Corner Restoration Year of search By	
Location filed SEC OF STATE		
Monument SET 1x36" 1.7. W/BRISS CAP PROPORTIONALLY		
<u> </u>	PAGE 199	
54/53		
1928		7.1.
Bearing Trees, Reference Objects Species BAISAM BAISAM	Bearing Trees, Reference	Objects
Diameter 6" 10"	With the second	
Bearing 533-456 575W		
Distance 95 Us 74 UKS		
Subsequent Corner Restoration Year surveyed	Evidence of Subsequent Corner Year of search By	
		alliationet women i magnetica analogica proprieta e e e e e e e e e e e e e e e e e e
Remonumentation certificate prepared	Ву	remonstration of page of page of the control of the