Index No. D /0-// CASS COUNTY LAN	ND CORNER RECORD	
T. 142 R. 28 M. 57H Coordinates: X	Υ	
E-SW 164 Corner common to sections 4		
AP#3 TR 1606	NG SURVEYS	
Original Government Survey	Original Evidence Found	1
Vac surveyed 1926 TR 1606	Year of searchBy	+ +
Original monument 1X36 11 Aug BASS 54 6	Monument found	
Bearing Trees	Original Bearing Trees Found	O = Corner
Species	_ Species	
Diameter	_ Diameter	
Bearing ——————————		
Distance	Distance	
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration	
Year surveyed By	Year of searchBy	
Location filed		
Monument		
Bearing Trees, Reference Objects	Bearing Trees, Reference	e Objects
Species		
Diameter	\$1	
Bearing		
Bearing		
Bearing		
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing Distance	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found
Bearing	Evidence of Subsequent Corner	Restoration Found