


Index No. G 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 11 Corner common to sections 1112



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument POST

Bearing Trees

Species	<u>W. PINE</u>	<u>SPRUCE</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>S55E</u>	<u>S35W</u>	_____
Distance	<u>15 LKS</u>	<u>27 LKS</u>	_____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK 'B' P. 214-219
 Monument SET HUB PROPORTIONALLY SET IRON
1919, E.B. HIRST COUNTY BOOK 'C' P. 342 FND I.M.
1916 - also on micro film - roll 105 BK 55 P. 19
set I.M. and B.T.S.

Bearing Trees, Reference Objects

Species	<u>MAPLE</u>	<u>MAPLE</u>	_____
Diameter	<u>6"</u>	<u>16"</u>	_____
Bearing	<u>S85W</u>	<u>S75E</u>	_____
Distance	<u>31.70'</u>	<u>37.00'</u>	_____

1916 ties

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO
FND 2" I.P. AT PROPORTIONAL POSITION
DID NOT SET ANOTHER IRON

Bearing Trees, Reference Objects

Species	<u>MAPLE</u>	<u>MAPLE</u>	_____
Diameter	<u>16"</u>	<u>8"</u>	_____
Bearing	<u>S78-15E</u>	<u>S41-30W</u>	_____
Distance	<u>57 LKS</u>	<u>93 LKS</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____