


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____ 1/4 _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Certificate of Location of Government Corner filed in Cass County

By _____


Recorders Office as Document _____

Date _____

Index No. J 15

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5th Coordinates: X _____ Y _____
N^o 4 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1879

Original monument rest

Bearing	Trees
Species <u>ELM</u>	<u>MAPLE</u>
Diameter <u>13"</u>	<u>6"</u>
Bearing <u>N10W</u>	<u>S16W</u>
Distance <u>8 LKS</u>	<u>23 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1916 By JOHN Curo

Location filed COUNTY SURVEY RECORD BOOK "B" P. 220-242

Monument FND OLD GOVT B.T.S SET IRON MONUMENT
(ELM N.W. 15 A BASSWOOD)
1916 - H.F. Baldwin - microfilm - roll 115 BK 78 P. 46
Fnd GOVT B.T.S P. 40 set F.M.

Evidence of Subsequent Corner Restoration

Year of search 1928 By GLO

FND 2" IR. W/ CAP SET BY COUNTY SURVEYOR
MARKED (AP: 1/4 S10
1/4 S15
1928

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>ELM</u>	<u>BASSWOOD</u>
<u>7"</u>	<u>8"</u>
<u>N20-45E</u>	<u>S38-15E</u>
<u>55 LKS</u>	<u>75 LKS</u>

Subsequent Corner Restoration

Year surveyed 1959 By CO. PWT Dept

Location filed CO. RD # 8 SP 11-615-01 BK 2

Monument found destroyed - reestablished from
1939 ties

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____