


Index No. J19

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 14 14 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument POST

Species	Bearing	Trees
<u>ELM</u>	<u>MAPLE</u>	
Diameter <u>13"</u>	<u>6"</u>	
Bearing <u>N16W</u>	<u>S16W</u>	
Distance <u>8 LKS</u>	<u>23 LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By E.B. HORST

Location filed COUNTY BOOK "C" P 343

Monument END GOVT POST & B.TS: ASH 8" NE 37.7', 9" PINE SE 49.1'

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO

NO ORIG EVIDENCE SLT 1X36" 1/2" W / BRASS CAP

14 511  
519  
1919

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

<u>ASH</u>	<u>W. PINE</u>
<u>8"</u>	<u>8"</u>
<u>N76-45E</u>	<u>S79-15E</u>
<u>57 LKS</u>	<u>74 LKS</u>

J-19 Subsequent Corner Restoration

Year surveyed 1983 (mark) By Freeman - Hummetsch

Location filed Survey Tech - Forester

Monument End monument in C of Road no B.T. Evidence.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_