Index No. L18

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X _____ Y _____

C.W. 1/16 Corner common to sections 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919

Original monument 1X36" I.P. w/ BRASS CAP C 1/16 C 5/14 1919

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

~~Species~~ 10" CEDAR POST

~~Diameter~~ 5" DIA

~~Bearing~~ 4' IN GROUND

~~Distance~~ ALONGSIDE IRON

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____