


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____ $1/4$ _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed: _____
Monument: _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. N 15

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X _____ Y _____
N 14 22 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument Post

Species	Bearing	Trees
<u>Poplar</u>	<u>FIR</u>	
Diameter <u>10"</u>	<u>6"</u>	
Bearing <u>N34E</u>	<u>S27W</u>	
Distance <u>12 LKS</u>	<u>26 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1928 By GZO

Location filed SEC. OF STATE

Monument SET 1X36" I.P. W/BRASS CAP PROPORTIONALLY.

1/4 515
532
1928

Evidence of Subsequent Corner Restoration

Year of search 1959 By Co Hunt Dept

Co RD # 8 SP 11-615-a BK # 2

I.P. found 292' w. of road

Bearing Trees, Reference Objects

Species <u>OAK</u>	<u>OAK</u>
Diameter <u>7"</u>	<u>6"</u>
Bearing <u>S73 30E</u>	<u>N60-15W</u>
Distance <u>61 LKS</u>	<u>63 LKS</u>

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____