


Index No. R 24-25

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 7 Corner common to sections 24, 25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>BIRCH</u>	<u>BIRCH</u>	
<u>7"</u>	<u>5"</u>	
<u>N8W</u>	<u>S11W</u>	
<u>19 LKS</u>	<u>26 LKS</u>	

Species	Bearing	Trees
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLD  
Location filed SEC. OF STATE  
Monument END 44 STAKE AND S.W. Q.T. STUMP, SET 1X36"  
11/2 WILBROS

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>MAPLE</u>	<u>ELM</u>	
<u>14"</u>	<u>24"</u>	
<u>S21E</u>	<u>N26-45W</u>	
<u>46 LKS</u>	<u>47 LKS</u>	

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - VINCENTS BOY LAKE HOMESITES  
W. J. SPAIN JR 1962

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_