


T. 142 R. 28 M. 514 Coordinates: X _____ Y _____
SMC on Corner common to sections 30
N 1/4 Line



EXISTING SURVEYS

Original Government Survey

Year surveyed 1928
Original monument 1x36" W.P.W. / BRASS SMC N 1/4 S N
cap 30 N
1928

Bearing Trees
Species ELM ELM
Diameter 12" 16"
Bearing N50-15E S64-45E
Distance 168 LKS 22 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1987 By Gary Stevenson
Location filed _____
Monument Found GLO monument in good condition.

1988 CERT OF LOCATION Doc # 304196

Bearing Trees, Reference Objects

Species Aspen Ash Ash
Diameter 12" 16" 8"
Bearing N5E S75E S20E
Distance 33.08' 142.00' 90.06'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Plat - Auditors Plat # 10 - Harold Cure - 1949

1988 Certificate - Gary Stevenson
Doc # 304196