


Index No. 53

CASS COUNTY LAND CORNER RECORD

T. 142 R. 20 M. 5th Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1928
Original monument 1x36" 1/4 P.W. BRASS C.N. 116 530
LAP 1928

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ELM
Diameter 14"
Bearing S76-15E
Distance 263 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1988 By Gary Stevenson
Certificate - Doc # 302550

Find GLO monument and BT

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Oak</u>	<u>9"</u>	<u>N89-35E</u>	<u>147.17'</u>
<u>Elm</u>	<u>24"</u>	<u>S76-23E</u>	<u>173.9'</u>
<u>Ash</u>	<u>5"</u>	<u>S55-40E</u>	<u>167.16'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Plat - Auditors Plat #10 - Harold Curo 1949
Certificate - Gary Stevenson - 1988

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____