

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_


= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument: |

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument: |

Index No. TR1

CASS COUNTY LAND CORNER RECORD

T. 14R R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E1/4 26 Corner common to sections 25, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	<u>POPULAR</u>	Bearing	<u>POPULAR</u>	Trees	_____
Diameter	<u>6"</u>		<u>7"</u>		_____
Bearing	<u>S32W</u>		<u>N20E</u>		_____
Distance	<u>30 LKS</u>		<u>41 LKS</u>		_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLD  
Location filed SEC. OF STATE  
Monument SET N36" 1/4 W/BRASS CAP 1/4  
SCHOOL HOUSE ON LINE 6.07 CH. SOUTH 526/525  
1919

Evidence of Subsequent Corner Restoration

Year of search 1932 By \_\_\_\_\_  
Co DITCH SURVEY BK 173 PG 80, Box 3  
Co DITCH BOOKS

Species	<u>POPULAR</u>	Bearing	<u>POPULAR</u>	Trees, Reference Objects	_____
Diameter	<u>4"</u>		<u>4"</u>		_____
Bearing	<u>S50-45E</u>		<u>S77-45W</u>		_____
Distance	<u>22 LKS</u>		<u>56 LKS</u>		_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_