


Index No. U 2

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S1/4 Corner common to sections 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1928  
Original monument 1x36" 1/2 P.W. / BRASS SW 1/4 570  
CAF 1928

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Poplar W. Oak  
Diameter 10" 18"  
Bearing N76-40E S73-55E  
Distance 373 LKS 357 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1988 By Gary Stevenson  
Certificate - Doc # 302552

Find GLO monument

old fence E: S

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Spruce Tam  
5" 7"  
N75W S5E  
89.40' 81.06'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Gary Stevenson - 1988

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_