


Index No. X5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 31 Corner common to sections 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. MAPLE</u>	<u>BASSWOOD</u>	_____
Diameter	<u>6"</u>	<u>10"</u>	_____
Bearing	<u>S47E</u>	<u>N81W</u>	_____
Distance	<u>70 LKS</u>	<u>22 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CURR, E. B. HORST
Location filed COUNTY BOOK B P 391-398
Monument SET SQUARE WOOD POST SET 2x4x8" IRON

Evidence of Subsequent Corner Restoration

Year of search 1928 By G. L. O.
FND 2x36" I.P. IN PLACE - SET 1x36" I.P. W/ BRASS
CAP FLUSH W/ & ROADS W/S
31/32
1928

Bearing Trees, Reference Objects

Species	<u>W. OAK</u>	<u>ELM</u>	_____
Diameter	<u>7"</u>	<u>6"</u>	_____
Bearing	<u>N7W</u>	<u>S37E</u>	_____
Distance	<u>51.80'</u>	<u>44.90'</u>	_____

Bearing Trees, Reference Objects

<u>BR. OAK</u>	_____	_____	_____
<u>10"</u>	_____	_____	_____
<u>S24-5W</u>	_____	_____	_____
<u>169 LKS</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____