


Index No. D17-18

CASS COUNTY LAND CORNER RECORD

T. 142 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC on Corner common to sections 2  
5 1/2 LINE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
 Original monument N36 1/2 W BATES SMC S  $\frac{52}{52}$  S  
CAD 1918

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees

Species MAPLE ELM \_\_\_\_\_  
 Diameter 18" 10" \_\_\_\_\_  
 Bearing N17-15E S87E \_\_\_\_\_  
 Distance 26 LKS 146 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_