


Index No. M7-8

CASS COUNTY LAND CORNER RECORD

T. 142 R. 29 M. 5TH Coordinates: X _____ Y _____

W-SE 1/64 Corner common to sections 17

NE COR TR 1418



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1926 _____

Original monument 1x36" I.P.W./BRASS A 1314
CAP NE COR
A 1418

Bearing Trees 517
1926

Species CEDAR POST _____

Diameter 6" X 7' _____

Bearing 2' IN GROUND _____

Distance ALONGSIDE ROAD _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____