dex No. E-16-17 CASS COUNTY LAN	D CORNER RECORD
142 R. 30 M. 5th Coordinates: X	Y
MCCorner common to sections 3:10	
FXISTIN	G SURVEYS
Original Government Survey	Original Evidence Found
ear surveyed 1918	Year of search By+
riginal monument ("436"). Pe w/Br. Cup	Monument found
Bearing Trees Species Elm Ash	Original Bearing Trees Found O = Corner Species
Diameter 6 7	Diameter
Bearing N894W 578W Distance 244 Llip 220 Llip	Bearing
Distance 277 Jus 220 des	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
ear surveyed 1963 By William OKERMAN.ocation filed	
Monument Found GLO monument in good condition.	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
pecies <u>Ash</u> <u>Ash</u> Diameter 7" <u>5"</u>	
Bearing <u>565W</u> <u>South</u>	
Subsequent Corner Restoration	W
Subsequent Corner Restoration ear surveyed By ocation filed lonument	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration aar surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ar surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration our surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration our surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration aar surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration aar surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration aar surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found