


T. 142 R. 30 M. 5TH Coordinates: X _____ Y _____
MC# 8 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search 1918 By GLO
Monument found None

Bearing Trees	
Species <u>Oak</u>	<u>Oak</u>
Diameter <u>10</u>	<u>12</u>
Bearing <u>N7W</u>	<u>S29W</u>
Distance <u>55 lks</u>	<u>38 lks</u>

Original Bearing Trees Found	
Species <u>Oak stp.</u>	<u>Oak stp</u>
Diameter <u>14</u>	<u>16</u>
Bearing <u>S29W</u>	<u>N7W</u>
Distance <u>38 lks</u>	<u>55 lks</u>

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed _____
Monument Set 1" x 36" I.P. w/Br. Cap for W.C. 5.50 chains west of original.

Evidence of Subsequent Corner Restoration

Year of search 1935 By GLO
Found monument and BTs for W.C. as per 1918 survey.

Bearing Trees, Reference Objects

Species <u>Ash</u>	<u>Elm</u>
Diameter <u>10</u>	<u>8</u>
Bearing <u>S 30 1/4 W</u>	<u>N 68 1/4 W</u>
Distance <u>60 lks</u>	<u>39 lks</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - LEECH LAKE PARK
CHAS. MURRAY 1924

CERTIFICATE - BILL OKERMAN - 1970
Set 2" x 60" galvanized steel monument with brass cap. 13" Ash N12W 40.70'; 12" Elm N43E 16.50'; 5" Elm S61E 11.00'