


Index No. J9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 17 Corner common to sections B, 9, 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees

Species	<u>Birch</u>	<u>Birch</u>	_____	_____
Diameter	<u>6</u>	<u>7</u>	_____	_____
Bearing	<u>N75E</u>	<u>N10W</u>	_____	_____
Distance	<u>88 lks</u>	<u>141 lks</u>	_____	_____

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed \_\_\_\_\_

Monument Fd. 3" square wood post i blazed  
lines N-S-E-W. No evidence found of BTs.  
Set 2" x 36" i.p. w/ Br. Cap

Evidence of Subsequent Corner Restoration

Year of search 1970 By William OKerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Oak</u>	<u>Oak</u>	<u>Oak</u>
Diameter	<u>6</u>	<u>5</u>	<u>5</u>	<u>8</u>
Bearing	<u>N35 3/4 E</u>	<u>S34 1/2 E</u>	<u>S39 W</u>	<u>N34 1/2 W</u>
Distance	<u>72 lks</u>	<u>29 lks</u>	<u>85 lks</u>	<u>59 lks</u>

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Oak</u>	_____	_____
Diameter	<u>10"</u>	<u>7"</u>	_____	_____
Bearing	<u>N46 W</u>	<u>S22 W</u>	_____	_____
Distance	<u>52.00'</u>	<u>61.70'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1970

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_