


Index No. J-K-14-15

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
AMC Corner common to sections 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1935  
Original monument 1" x 3/8" I.P. w/Br. Cap  
*LOT 6  
S15  
L7  
1935* / AMC

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Elm</u>	<u>Elm</u>	_____	_____
Diameter	<u>7</u>	<u>8</u>	_____	_____
Bearing	<u>S72 1/2 W</u>	<u>N77 1/4 W</u>	_____	_____
Distance	<u>84 lks</u>	<u>131 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1981 By GHS  
Location filed \_\_\_\_\_  
Monument Found both 1935 BTS - position for corner now falls in lake - set 1/2" iron pipe for reference on line 31.07 feet west of true. Ties to 1935 BTS.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Elm</u>	_____	_____
Diameter	<u>12"</u>	<u>18"</u>	_____	_____
Bearing	<u>N65W</u>	<u>S50W</u>	_____	_____
Distance	<u>56.55'</u>	<u>27.32'</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_