


Index No. N 13

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 21 Corner common to sections 15, 16, 21, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>6</u>	<u>6</u>	<u>6</u>	<u>12</u>
Bearing	<u>N66E</u>	<u>S6E</u>	<u>N49W</u>	<u>N12W</u>
Distance	<u>12 lks</u>	<u>20 lks</u>	<u>7 lks</u>	<u>30 lks</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLD  
Location filed \_\_\_\_\_  
Monument Set 2" x 36" l.p. w/ Br. cap at proportional point - no evidence of original. Dug pits in each section

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_