


Index No. 0-14-15

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC No line Corner common to sections 2-2



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1" x 3/16" I.P. w/Br. Cap

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees
Species <u>Elm</u>	<u>Elm</u>	
Diameter <u>10</u>	<u>4</u>	
Bearing <u>N83W</u>	<u>S54 1/4 W</u>	
Distance <u>35 lks</u>	<u>21 lks</u>	

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1965 By DNR - Engineering  
Location filed Map notes in file  
Monument Found brass cap monument

Evidence of Subsequent Corner Restoration

Year of search 1965 By William Okerman  
Found GLO monument in good condition  
10" Elm N83W 23.10' now 12"

Bearing Trees, Reference Objects

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

<u>Oak</u>	_____	_____
<u>8"</u>	_____	_____
<u>N29E</u>	_____	_____
<u>13.20'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1965

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_