


Index No. Q-13-14

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
1/64 Corner common to sections 22



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1918
 Original monument 1" X 3/16" I.P. w/ Br. Cap

AP 4
 TR
 1363
 TR 1321

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1965 By DNR - Engineering
 Location filed map & notes in file
 Monument Found brass cap monument

Evidence of Subsequent Corner Restoration
 Year of search 1965 By William Okerman
 Found GLO monument in good condition.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
Elm Maple
9" 11"
S 81 W S 57 E
9.8' 5.9'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1965
Apr 2003 T. Freeman #21367
Cert. of Surv. shows Mon. Found

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____