


Index No. Q-6-7

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
SMC Corner common to sections 20



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1918
 Original monument 1" x 3/16" i.p. w/br. cap for w.c.
 True point 0.06 chains west

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees

| Species | N. Pine | S. Pine | Trees |
|----------|------------------------------------|-----------------------------------|-------|
| Diameter | 9 | 5 | _____ |
| Bearing | S 57 ³ / ₄ E | N 8 ¹ / ₂ E | _____ |
| Distance | 11 lbs | 58 lbs | _____ |

Original Bearing Trees Found

| Species | _____ | _____ | _____ |
|----------|-------|-------|-------|
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| | | | |
|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
