


Index No. Q-R 5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 23 Corner common to sections 19, 20



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1873  
 Original monument POST

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Bearing Trees**  
 Species W. Pine \_\_\_\_\_  
 Diameter 6" \_\_\_\_\_  
 Bearing S 20 W \_\_\_\_\_  
 Distance 17 lks \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1917 By GLO  
 Location filed \_\_\_\_\_  
 Monument Set 1" x 3/8" I.P. w/ Br. cap on record bearing - no evidence found of original.

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Raised mound of stone west of corner.

**Bearing Trees, Reference Objects**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Bearing Trees, Reference Objects**  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Re-monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_