


T. 142 R. 30 M. 574 Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search 1917 By GLO
Monument found None

Species	Bearing Trees			
	W. Pine	Y. Pine	Y. Pine	Elm
Diameter	<u>36</u>	<u>24</u>	<u>24</u>	<u>14</u>
Bearing	<u>S59W</u>	<u>S20E</u>	<u>N41W</u>	<u>N22E</u>
Distance	<u>19 lks</u>	<u>24 lks</u>	<u>100 lks</u>	<u>87 lks</u>

Species	Original Bearing Trees Found			
	W. Pine stp	Y. Pine stp	Elm stp	Y. Pine stp
Diameter	<u>36</u>	<u>28</u>	<u>18</u>	<u>24</u>
Bearing	<u>S50 1/2 W</u>	<u>S15 1/2 E</u>	<u>N24 1/2 E</u>	<u>N39 W</u>
Distance	<u>20 lks</u>	<u>27 lks</u>	<u>81 lks</u>	<u>108 lks</u>

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed _____
Monument Set 1" x 36" I.P. w/ Br. Cap from the
stumps of all 4 original BTs.

Evidence of Subsequent Corner Restoration

Year of search 1970 By William Okerman
Found GLO monument in good condition.
Sept. 1911, Twp rd order shows no survey

Bearing Trees, Reference Objects

Species	Willow	Basswood	W. Oak	W. Oak
	Diameter	<u>4</u>	<u>6</u>	<u>6</u>
Bearing	<u>N1 1/2 E</u>	<u>S4 E</u>	<u>S46 1/2 W</u>	<u>N76 3/4 W</u>
Distance	<u>56 lks</u>	<u>36 lks</u>	<u>95 lks</u>	<u>88 lks</u>

Bearing Trees, Reference Objects

Elm	Ash	Elm	Oak
<u>8'</u>	<u>7"</u>	<u>7"</u>	<u>15"</u>
<u>N80 W</u>	<u>N17 E</u>	<u>S31 E</u>	<u>S46 W</u>
<u>10.60'</u>	<u>9.60'</u>	<u>36.10'</u>	<u>63.00'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - FIRST ADDITION TO HEATHMAN ESTATES
B.R. BURTON 1977
PLAT - FAY'S HARBOR
WALTER E. CURA 1977
CERTIFICATE - BILL OKERMAN - 1970