


Index No. T-10-11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
1/4 Corner common to sections 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1" x 3/16" I.P. w/ Br. Cap

APT
TR
1726
TR 1297

Bearing Trees

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Original Evidence Found

Year of search 1990 By USFS
Monument found GLO Brass Cap

Original Bearing Trees Found

Species	<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>	<u>S. gn Post</u>
Diameter	<u>13"</u>	<u>8"</u>	<u>10"</u>	_____
Bearing	<u>N47°E</u>	<u>S20°E</u>	<u>S5°W</u>	<u>North</u>
Distance	<u>85.50</u>	<u>71.00</u>	<u>91.30</u>	_____
	<u>60d spk</u>	<u>60d spk</u>	<u>60d spk</u>	_____

Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO
Location filed CCSO
Monument Found GLO Brass cap, flush,
1' s of & Co Rd. #153. 1990
witness trees all good.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

T-10, 11

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____

Filed at _____

By _____

Date _____