Index No. T-11-12

# CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
1/64 Corner common to sections 28




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1918
Original monument 1"x36" I.P. w/Br. Cap
AP+ TR 1345

### Original Evidence Found

Year of search 1985 By USFS
Monument found GLO Brass Cap

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | R. Oak | N. Pine | N. Pine | |
| Diameter | 8" | 18" | 16" | |
| Bearing | N75°W | S55°E | S36°W | |
| Distance | 48.25 | 39.25 | 45.70 | |
| | 60d spk | 60d spk | 60d spk | |

### Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO
Location filed CCSO
Monument Found GLO Brass cap monument and 1985 witnesses in good condition

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

T-11, 12

### Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed
Monument

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____